

Inspection Software Systems  
Pleasant Hill, CA

| Row | Tube | % Wall Loss | ID | OD | Defect Code | Nominal Wall | Actual Wall Loss | Remaining Wall | LOCATION   | COMMENT                   |
|-----|------|-------------|----|----|-------------|--------------|------------------|----------------|------------|---------------------------|
| 1   | 1    | 0%          |    |    | NRI         | 0.134        | 0.000            | 0.134          |            | No Recordable Indications |
| 1   | 2    | 28%         |    |    | WLL         | 0.134        | 0.038            | 0.096          | 367.874in. |                           |
| 1   | 3    | 40%         |    |    | WLL         | 0.134        | 0.054            | 0.080          | 368.031in. |                           |
| 1   | 4    | 29%         |    |    | PIT         | 0.134        | 0.039            | 0.095          | 286.024in. | Pitting                   |
| 2   | 1    | 17%         |    |    | WLL         | 0.134        | 0.023            | 0.111          | 329.449in. |                           |
| 2   | 2    | 17%         |    |    | WLL         | 0.134        | 0.023            | 0.111          | 388.976in. |                           |
| 2   | 3    | 10%         |    |    | PIT         | 0.134        | 0.013            | 0.121          | 298.130in. | Pitting                   |
| 2   | 4    | 38%         |    |    | WLL         | 0.134        | 0.051            | 0.083          | 349.016in. |                           |
| 2   | 5    | 13%         |    |    | PIT         | 0.134        | 0.017            | 0.117          | 138.110in. | Pitting                   |
| 2   | 6    | 30.5%       |    |    | PIT         | 0.134        | 0.041            | 0.093          | 331.831in. | Pitting                   |
| 3   | 1    |             |    |    | OBS         |              |                  |                | 331.063in. | Obstructed                |
| 3   | 2    | 0%          |    |    | NRI         | 0.134        | 0.000            | 0.134          |            | No Recordable Indications |
| 3   | 3    | 19.9%       |    |    | WLL         | 0.134        | 0.027            | 0.107          | 497.480in. |                           |
| 3   | 4    | 22.4%       |    |    | WLL         | 0.134        | 0.030            | 0.104          | 482.618in. |                           |
| 3   | 5    | 28.4%       |    |    | WLL         | 0.134        | 0.038            | 0.096          | 484.843in. |                           |
| 3   | 6    | 21.7%       |    |    | WLL         | 0.134        | 0.029            | 0.105          | 425.079in. |                           |
| 3   | 7    | 21.4%       |    |    | WLL         | 0.134        | 0.029            | 0.105          | 432.835in. |                           |
| 4   | 1    | 20.7%       |    |    | WLL         | 0.134        | 0.028            | 0.106          | 464.783in. |                           |
| 4   | 2    | 22.3%       |    |    | WLL         | 0.134        | 0.030            | 0.104          | 556.063in. |                           |
| 4   | 3    | 45.2%       |    |    | PIT         | 0.134        | 0.061            | 0.073          | 230.906in. | Pitting                   |
| 4   | 4    | 19.2%       |    |    | PIT         | 0.134        | 0.026            | 0.108          | 519.547in. | Pitting                   |
| 4   | 5    | 19.2%       |    |    | PIT         | 0.134        | 0.026            | 0.108          | 415.354in. | Pitting                   |
| 4   | 6    | 15.3%       |    |    | PIT         | 0.134        | 0.021            | 0.113          | 378.996in. | Pitting                   |
| 4   | 7    | 14.2%       |    |    | WLL         | 0.134        | 0.019            | 0.115          | 477.776in. |                           |
| 4   | 8    | 20.7%       |    |    | WLL         | 0.134        | 0.028            | 0.106          | 391.949in. |                           |
| 5   | 1    | 44.4%       |    |    | WLL         | 0.134        | 0.059            | 0.075          | 445.472in. |                           |
| 5   | 2    | 37.7%       |    |    | WLL         | 0.134        | 0.051            | 0.083          | 375.039in. |                           |
| 5   | 3    | 25.3%       |    |    | WLL         | 0.134        | 0.034            | 0.100          | 414.311in. |                           |
| 5   | 4    | 41.8%       |    |    | WLL         | 0.134        | 0.056            | 0.078          | 391.201in. |                           |
| 5   | 5    | 40.4%       |    |    | WLL         | 0.134        | 0.054            | 0.080          | 414.665in. |                           |
| 5   | 6    | 32%         |    |    | WLL         | 0.134        | 0.043            | 0.091          | 450.650in. |                           |
| 5   | 7    | 22.4%       |    |    | WLL         | 0.134        | 0.030            | 0.104          | 419.547in. |                           |
| 5   | 8    | 22.7%       |    |    | WLL         | 0.134        | 0.030            | 0.104          | 372.402in. |                           |
| 6   | 1    | 47.1%       |    |    | WLL         | 0.134        | 0.063            | 0.071          | 584.193in. |                           |
| 6   | 2    | 25.5%       |    |    | WLL         | 0.134        | 0.034            | 0.100          | 420.276in. |                           |
| 6   | 3    | 38%         |    |    | WLL         | 0.134        | 0.051            | 0.083          | 414.685in. |                           |
| 6   | 4    | 19.6%       |    |    | WLL         | 0.134        | 0.026            | 0.108          | 438.228in. |                           |
| 6   | 5    | 22.3%       |    |    | WLL         | 0.134        | 0.030            | 0.104          | 392.283in. |                           |
| 6   | 6    | 19.8%       |    |    | WLL         | 0.134        | 0.027            | 0.107          | 60.098in.  |                           |

Inspection Software Systems  
Pleasant Hill, CA

| Row | Tube | % Wall Loss | ID | OD | Defect Code | Nominal Wall | Actual Wall Loss | Remaining Wall | LOCATION   | COMMENT |
|-----|------|-------------|----|----|-------------|--------------|------------------|----------------|------------|---------|
| 6   | 7    | 18%         |    |    | WLL         | 0.134        | 0.024            | 0.110          | 162.047in. |         |
| 7   | 1    | 25.9%       |    |    | WLL         | 0.134        | 0.035            | 0.099          | 391.713in. |         |
| 7   | 2    | 16.7%       |    |    | WLL         | 0.134        | 0.022            | 0.112          | 213.524in. |         |
| 7   | 3    | 19.1%       |    |    | WLL         | 0.134        | 0.026            | 0.108          | 407.047in. |         |
| 7   | 4    | 23.1%       |    |    | PIT         | 0.134        | 0.031            | 0.103          | 576.496in. | Pitting |
| 7   | 5    | 26.9%       |    |    | WLL         | 0.134        | 0.036            | 0.098          | 407.598in. |         |
| 7   | 6    | 26.7%       |    |    | WLL         | 0.134        | 0.036            | 0.098          | 459.193in. |         |
| 8   | 1    | 39.6%       |    |    | WLL         | 0.134        | 0.053            | 0.081          | 391.043in. |         |
| 8   | 2    | 13.8%       |    |    | WLL         | 0.134        | 0.018            | 0.116          | 499.232in. |         |
| 8   | 3    | 23.2%       |    |    | WLL         | 0.134        | 0.031            | 0.103          | 417.795in. |         |
| 8   | 4    | 41.8%       |    |    | WLL         | 0.134        | 0.056            | 0.078          | 438.346in. |         |